Table 1 Summary of Results

| SAMPLIN | INITIAL SAMPLING RESULTS | | | RE-SAMPLING RESULTS ded Level = 20ppb | | | CORRECTIVE ACTIONS | POST REMEDIATION SAMPLING RESULTS Recommended Level = 20ppb | | | |
|---------------------------------|--------------------------------------|------------------------------------|-------------------------|---------------------------------------|--|--|--------------------------|--|---------------------------|-------------------------------------|---|
| CATEGORY Water Intended For: | SAMPLE ID | Outlet Description | First Draw (ppb) | Retest required? | Date Fixture Secured? (See Note 1) | Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb) | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb) | Description | First Draw (ppb) (See note 2) | Follow up Flush - Collected 30 seconds afte First Draw Sampling (ppb) |
| SAMPLING DATE RESULTS DATE | | | 9/15/2018 10/10/2018 | | | mm/dd/yyyy | 10/22/2018 10/26/2018 | 10/26/2018 | | | mm/dd/yyyy mm/dd/yyyy |
| Drinking | N/A | N/A | | N/A | N/A | N/A | N/A | N/A | | N/A | N/A |
| Cooking | N/A | N/A | | N/A | N/A | N/A | N/A | N/A | | N/A | N/A |
| Washing | NSGB-692-RM-HHW-A-FD (BLDG 692-1) | Sink in general area. | Non Detect | No | N/A | N/A | N/A | N/A | | N/A | N/A |
| Washing | NSGB-692-RM-HHW-B-FD (BLDG 692-2) | Outdoor sink outside of back door. | 41 | Yes | 10/12/2018 | N/A | 6.3 | 1.4 | Fixture removed 12/10/18. | N/A | N/A |

Notes:

1 Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

1 Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

² Post-remediation sampling was initially conducted on (DATE). Additional (ACTIONS) were implemented and final results below recommended level of 20 ppb for samples collected on (DATE) are shown on the table.

| Table 2. Summary Statistics | | | | | | | | | | |
|-----------------------------|------------------|--|---------------------|--|------------------|--|--|--|--|--|
| CATEGORY | INITIAL SAMPLING | | RE-SAMPLING RESULTS | POST REMEDIATION RESULTS | | | | | | |
| | | Recommended Level = 20ppb | | | | | | | | |
| | First Draw (ppb) | Water Fountain Follow up Flush Sample - Collected day before First | First Draw (ppb) | Follow up Flush - Collected 30 seconds after First Draw Sampling | First Draw (ppb) | | | | | |
| | | Draw Sampling (ppb) | | (ppb) | | | | | | |
| Total Drinking | 0 | 0 | 0 | 0 | 0 | | | | | |
| Total Drinking > 20 ppb | 0 | 0 | 0 | 0 | 0 | | | | | |
| Total Cook/Brush | 0 | 0 | 0 | 0 | 0 | | | | | |
| Total Cook/Brush > 20 ppb | 0 | 0 | 0 | 0 | 0 | | | | | |
| Total Washing | 2 | 0 | 1 | 1 | 0 | | | | | |
| Total Washing > 20 ppb | 1 | 0 | 0 | 0 | 0 | | | | | |
| Total Samples | 2 | 0 | 1 | 1 | 0 | | | | | |
| Total Samples > 20 ppb | 1 | 0 | 0 | 0 | 0 | | | | | |